

VOLLGEWINDE ("V") und TEILGEWINDE ("T")

Spanplattenschrauben

Senkkopf, pozidrive

celý závit ("V") a čiastočný závit ("T")


Drevoskrutka

Zapustená hlava, pozidrive

ARTIKEL

100

	Stahl	
MATERIAL		
OBERFLÄCHE		
verz.		gelb



d 1	3	3,5	4	4,5	5	6	

I								
12	V	LG	V	LG	V	LG		
13	V	LG	V	LG	V	LG		
15	V	LG	V	LG	V	LG		
16	V	LG	V	LG	V	LG	V	LG
17	V	LG	V	LG	V	LG	V	LG
20	V	LG	V	LG	V	LG	V	LG
25	V	LG	V	LG	V	LG	V	LG
30	V	LG	VT	LG	VT	LG	V	LG
35	V	LG	VT	LG	VT	LG	VT	LG
40	VT	LG	VT	LG	VT	LG	VT	LG
45	T	LG	VT	LG	VT	LG	VT	LG
50			VT	LG	VT	LG	VT	LG
55			VT	LG	T	LG	T	LG
60			VT	LG	VT	LG	VT	LG
70			VT	LG	VT	LG	VT	LG
80			T	LG	T	LG	T	LG
90							VT	LG
100							T	LG
110							T	LG
120							T	LG
130							T	LG
140							T	LG
150							T	LG
160							T	LG
180							T	LG
200							T	LG
220							T	LG
240							T	LG
260							T	LG
280							T	LG
300							T	LG

Pan Head, pozidrive


ARTIKEL

100

Drevoskrutka polguľ'atá hlava

pozidrive

	Stahl	
MATERIAL		
OBERFLÄCHE		
verz.		gelb



"verzinkt" 411

"gelb" 441

<i>d</i> 1	3	3.5	4	4.5	5	6

[illegible]

[illegible]